

Pressure/Torque conversion chart

Link tool 18

Pressure Druk / Pression		Torque Aanhaalmoment / Couple de serrage		Pressure Druk / Pression
Psi	Ft.Lbs.	KGM	NM	Bar
1500	2980	412	4040	104
1600	3170	438	4297	110
1800	3550	491	4812	124
2000	3930	544	5328	138
2200	4334	599	5875	152
2400	4738	655	6423	165
2600	5142	711	6970	179
2800	5546	767	7518	193
3000	5950	823	8066	207
3200	6350	878	8608	220
3400	6750	934	9150	234
3600	7150	989	9693	248
3800	7550	1044	10235	262
4000	7950	1099	10777	276
4200	8348	1155	11317	290
4400	8746	1210	11856	303
4600	9144	1265	12396	317
4800	9542	1320	12935	331
5000	9940	1375	13475	345
5200	10340	1430	14017	358
5400	10740	1485	14559	372
5600	11140	1541	15101	386
5800	11540	1596	15644	400
6000	11940	1651	16186	414
6200	12332	1706	16717	427
6400	12724	1760	17249	441
6600	13116	1814	17780	455
6800	13508	1868	18311	468
7000	13900	1922	18843	482
7200	14282	1975	19361	496
7400	14664	2028	19879	510
7600	15046	2081	20396	524
7800	15428	2134	20914	538
8000	15810	2187	21432	552
8200	16192	2239	21950	565
8400	16574	2292	22468	579
8600	16956	2345	22986	593
8800	17338	2398	23503	607
9000	17720	2451	24021	620
9200	18120	2506	24563	634
9400	18520	2561	25106	648
9600	18920	2617	25648	662
9800	19320	2672	26190	676
10000	19720	2727	26732	690

Revised: 08/2000