

Pressure/Torque conversion chart

Link tool 2

Pressure Druk / Pression		Torque Aanhaalmoment / Couple de serrage		Pressure Druk / Pression
Psi	Ft.Lbs.	KGM	NM	Bar
1500	255	35	346	104
1600	272	38	369	110
1800	306	42	415	124
2000	340	47	461	138
2200	376	52	510	152
2400	412	57	559	165
2600	448	62	607	179
2800	484	67	656	193
3000	520	72	705	207
3200	552	76	748	220
3400	584	81	792	234
3600	616	85	835	248
3800	648	90	878	262
4000	680	94	922	276
4200	714	99	968	290
4400	748	103	1014	303
4600	782	108	1060	317
4800	816	113	1106	331
5000	850	118	1152	345
5200	884	122	1198	358
5400	918	127	1244	372
5600	952	132	1291	386
5800	986	136	1337	400
6000	1020	141	1383	414
6200	1054	146	1429	427
6400	1088	150	1475	441
6600	1122	155	1521	455
6800	1156	160	1567	468
7000	1190	165	1613	482
7200	1224	169	1659	496
7400	1258	174	1705	510
7600	1292	179	1751	524
7800	1326	183	1798	538
8000	1360	188	1844	552
8200	1394	193	1890	565
8400	1428	197	1936	579
8600	1462	202	1982	593
8800	1496	207	2028	607
9000	1530	212	2074	620
9200	1566	217	2123	634
9400	1602	222	2172	648
9600	1638	227	2220	662
9800	1674	232	2269	676
10000	1710	236	2318	690

Revised: